

STRESS POINT

Create a loop within a foot of the transducer and secure with wire tie.

Secure the cable to a solid location about three feet from the loop using wire tie.

To unplug PACK-CON Cable:

- A.** Lift Tab to release cable from transducer.
- B.** Grab back end of connector and pull straight out of transducer.
- C.** Make sure Gray cap remains on end of plug.

DO NOT TWIST OR ANGLE WHEN UNPLUGGING



SHIELD

EARTH GROUND

RED
BLACK
WHITE



+5 GND SI

DIGITAL / ANALOG



Three Conductor
Shielded Cable
#20 AWG

**MICRO
CONTROL
SYSTEMS**

5580 Enterprise Pkwy. Fort Myers, FL 33905 USA
Phone: 239-694-0089 • www.mcsccontrols.com
support@mcsccontrols.com