



NEWS RELEASE

# Product Update Announcement



Effective: 10-13-2020

## MAGNUM KEYPAD CHANGES

*Improving our products - Latest Version 10.3*





**Keypad rev 10.0 and greater requires MCS-Magnum firmware 17.62I or greater and Bootloader version 1.01m or later.**



Ver. 10.2  
Ribbon Cable was eliminated

### Ver. 10.3 - Gasket added

◀ On the new Mag-Keypads (Interface 10.3) we have added a Gasket between the Keypad and the LCD/Interface board to prevent debris from entering.



◀ LCD/Interface board added over Gasket and sealed to prevent debris from entering.

Any questions regarding this release, contact [sales@mcscontrols.com](mailto:sales@mcscontrols.com)  
Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2020.  
Copying or distributing this document is prohibited unless expressly authorized by MCS.