



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 14.01D 02/27/2014

Updates from previous versions:

Bug Fixes:

1. In ALL MicroMag config types V12 on the BMS Points screen under the Writable Points section setpoint 22 should be listed as writable on the setpoint grid. Resolution: Add setpoint 22 to the test that checks for the writable setpoint ranges in the Update BMS function.
2. In HVAC, CENT, RTU config types when converting from V11 to V14 cfg files the condenser reset si field was not being set to Not Used during the conversion. Resolution: Change the source code to set the condenser reset SI memory location to 255 during the conversion.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.