



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 8.00N 04/26/2011

Updates from previous versions:

Bug Fixes:

1. Removed the automatic conversion function when changing the display or refrigerant types. Instead of displaying a pop-up with a prompt for the user to automatically convert the setpoints, now a warning message will appear telling the user to manually change the setpoint value to agree with the new display or refrigerant type.
2. Relay Output, Analog Output, and Sensor Input point naming bug fix to be compatible with BACNET.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.