



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 8.00P 05/03/2011

Updates from previous versions:

Bug Fixes:

1. Removed the RO Sequence Check for all PAO configurations.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.