



SOFTWARE RELEASE NOTES

MCS-CONFIG
Version 8.00T
06/02/2011

Updates from previous versions:

Bug Fixes:

1. Corrected issue with rows not changing the background color when changing from tandem EXV to non-tandem.
2. Changed 'Filter (Time in SEC)' column on the SI screen to display values of 255 as 0.
3. Increased 'Lockout Delay (HRS)' maximum selection from 12 to 15.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.