



SOFTWARE RELEASE NOTES

MCS-CONFIG
Version 8.00Y
07/05/2011

Updates from previous versions:

New Features:

1. Added the modbus display type wizard form to the SI screen.

Bug Fixes:

1. Fixed bug that caused an infinite loop that locks up MCS-Config when changing the compressor type from "Recip comp w/oil" or "Recip comp w/o oil" to any other compressor type other than "Recip comp w/o oil" or "Recip comp w/oil".

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.