



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 8.10C 08/08/2011

Updates from previous versions:

New Features:

1. Added two new features to the setup screen: yes or no selections called 'Factory Startup Required' and 'Run Hour Lockout Required'.

Factory Startup Required	☒ Yes ☐ No	
Run Hour Lockout Required	☒ Yes ☐ No	
Number of Hours	32767	

Bug Fixes:

1. Fixed the Circuit/Compressor Relay Output sequence list to display the oil pump for screw compressors with external oil pump.
2. Changed logic so Purge Oil and Purge Vent only show up with CENT and HVAC configs (with centrifugal compressor type).
3. Changed Circuit/Compressor Relay Output sequence list to not display for PAO or LWC config types.
4. If any Circuit/Compressor Relay Output sequence overlaps another circuit then a warning message will display to let the user know the RO count and sequence is wrong and where to go to fix it.
5. Changed the "Config Type" drop down list in the System screen to more uniformly and accurately describe the config type. (i.e. "Chiller V8 Cfg" now is "HVAC Mag V8").
6. Fixed printing error where the Closed=Off setting (if a digital input) does not print.
7. Fixed error when trying to print a config that was opened by double clicking the file instead of opening through the MCS-Config program (was causing run time error #5: Invalid Procedure Call or Argument).

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.