



SOFTWARE RELEASE NOTES

MCS-CONFIG
Version 8.10D
08/08/2011

Updates from previous versions:

Bug Fixes:

1. Changed the necessary authorization level for 'Factory Startup' and 'Run Hour Lockout Required' to be Factory Level and not their own authorization codes.
2. Set the tab order correctly on the Setup screen so each time tab is pressed the focus goes to the next editable field on the screen

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.