



SOFTWARE RELEASE NOTES

MCS-CONFIG
Version 8.10L
10/04/2011

Updates from previous versions:

Bug Fixes:

1. Fixed bug on the Sensor Fault Low and Sensor Fault High columns on the SI grid, that was not letting the user enter values correctly.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.