



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 9.03Q 06/27/2012

Updates from previous versions:

Bug Fixes:

1. In MicroMag config types when MCS-Config is installed on the user's PC and a config file is double clicked to open it in MCS-Config the authorization popup is not displayed and the menu buttons are not enabled as it should be. This error has been fixed.
2. In all config types, if the user opens MCS-Config and then closes it with the top right corner red X the authorization popup window does not close. This has been fixed by inserting a test if closed in the main MDIForm to unload the auth popup to close it.
3. In RTU config types on the MAG RTU info screen under the ventilation info section, the panels have been rearranged so the Return Fan & Relief Damper and Supply Fan panels are next to each other.
4. In HVAC, RTU, CENT, LWC, REFR config types, when the user clicks the button to create config files on the BMS Points screen, the N2 file that is created has syntax errors in it and the boot file that is created must always be named config.csv. The syntax errors have been corrected.
5. In MicroMag config types, the 6 setpoint names in the MicroMagSetpointNames array have been changed.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.