



# SOFTWARE RELEASE NOTES

---

MCS-CONNECT  
Version 14.00R  
08/29/2013

## Updates from previous versions:

### New Features:

1. Added three new options to the User Logic Operands when selecting a Compressor type of operand in version 14 cfgs only had to create a new string array that is loaded only for v14.

### Bug Fixes:

1. Made a few small changes to the Graphic HTML Loader class to allow Graphics to work in Linux OS.
2. When switching between workspaces with the workspace menu the desktop was not being repainted and would leave "ghosts" of the previous desktop's internal frames. RESOLUTION- I added a repaint function call to the Info Tabbed Pane after every status init which is done after switching workspaces.
3. Matching RTU Heating state arrays with SW.
4. The SI, AO, and RO alarms are still showing the overall # of the point instead of the grid #.  
RESOLUTION - Changed the function to display the correct point # based on which IO board the sensor or relay is on.

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.