



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 15.00E
08/06/2014

Updates from previous versions:

New Features:

1. CPM User Logic: Adding CPM structures to User Logic classes

Bug Fixes:

1. The RO grid was not showing up on the desktop for MicroMag config types. This was caused by a referencing error when attempting to refresh the grid. I was looking at the wrong button header for the hide/show column. RESOLUTION - Changed the reference to the correct instance of button header.
2. The Control On column in the status grid for V14 CENT SW is not updating when the SI represented there is hidden. This is due to the lack of a check for this config type when refreshing this Sensor regardless of its viewability. RESOLUTION - I added a check for this cfg type in my refresh loop to update this SI value all the time.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.