



# SOFTWARE RELEASE NOTES

---

MCS-CONNECT  
Version 8.100  
05/04/2011

## Updates from previous versions:

### Bug Fixes:

1. Ensured the Alarm history popup works for REFR Software.
2. Corrected to display Circuit ID instead of Circuit # in REFR Software.
3. Changed User Logic ROs to correctly generate alarms when this feature is selected in MCS-Config

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

**Micro Control Systems, Inc.** 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.