



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.00C
06/07/2013

Updates from previous versions:

Bug Fixes:

1. Boiler grids were attempting to refresh themselves without being initialized due to:
 - a. incomplete test to determine if they need to be refreshed. RESOLUTION - Added a check to determine
 - b. the cfg type needs the Boiler grid refreshing matching the same check used when initializing.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.