



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.00K
07/18/2013

Updates from previous versions:

Bug Fixes:

1. To facilitate the auto print to file on lockout alarm functionality I had to add a test to all grid refresh functions to allow these functions to refresh all cells instead of just a partial refresh based on the count of the refresh loop. ex. Every third refresh. These parameters are only used in V11 and V14 cfg types.
2. The Graph setup is not correctly selecting DIs that were selected and saved to the Graph.ini file. RESOLUTION - Added code to the function that sets up the little SI Grid in the GraphSetupUI that checks the temp DI memory location and selects the check boxes of Sensors that are DIs and selected.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.