



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.00C
10/31/2014

Updates from previous versions:

Bug Fixes:

1. In the Modbus V13 packages added 2 new options to the special Combo Box. "Float-LSB, Float-MSB" are the 2 new options.
2. Changes to the Graphic XML Loader to improve the functionality of the new Java FX package widgets.
3. The service Panel was not initializing for V17 config types. This was caused by a lack of type checks in the Service Panel java class. RESOLUTION - added checks for this config type to allow initialization.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.