

CONTROL SOFTWARE RELEASE NOTES

MCS-CONNECT Version 17.00R 02/25/2015

Updates from previous versions:

New Features:

- 1. Added a state to the CPM Chiller State list: "OFF:NO PMP AVAIL"
- 2. Added a new "Lead?" column to the CPM Grid3 and the pumps groups grid. Displays "Yes" in the row that is the Lead.

Bug Fixes:

- 1. When the user highlights a row in the Basic RO Grid by clicking it the Advanced grid does not highlight. RESOLUTION Added code to highlight both grids rows when the user clicks either grid.
- 2. The user Defined RO UI was displaying incorrect values for v10 configs. This was caused by a change that was made to later versions of RO Eerom and was never made to the base class. RESOLUTION Added fix to match RO Eerom base class with its child classes.
- 3. The user Defined RO UI was displaying incorrect values for v10 configs. The Delay before On panel was being hidden incorrectly. The Delay before OFF Panel should have been hidden instead. RESOLUTION Hid the Delay before OFF panel and showed that Delay before ON panel.
- 4. The Ignition Temp column in the Mod Gas Grid in the Heat Status Frame for the MicoMag was showing the incorrect # of decimals. This was caused by an erroneous function call. RESOLUTION Removed the call and replaced with correct logic to display # of decimals based on Sensor Type 2.

Any questions regarding this release, contact: support@mcscontrols.com