



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 8.10R
08/17/2011

Updates from previous versions:

New Features:

1. Added 4 new states for the TurboCor logic:
2. Added subcooler code to valve states.

Bug Fixes:

1. Fixed bug where the Graph button is not being disabled when the user becomes un-authorized.
2. Corrected Boiler panel display issue.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.