



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.10C
01/07/2013

Updates from previous versions:

Bug Fixes:

1. In the SI Grid when the Sensor type combo box was initialized it was getting the manual status combo box values added to the beginning of its member list. This was due to a new combo box not being created after creating and initializing the manual status combo box. RESOLUTION - Created a new combo box before initializing it to have the sensor types in it.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.