



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 14.00E 06/07/2013

Updates from previous versions:

Bug Fixes:

1. Corrected problem with user logic digital input types not working. This problem was introduction into V14 by the changed made on the sensor type test to call the correct conversion function. The digital flag was not being set for user logic digital input types.
2. RTU-Modified function to initially unused comp relay indexes as "NOT USED". There were some indexes not being setup in RTU that are used in EXV code. Now with common EXV logic in these values need to be setup in all the projects that use it.
3. Corrected issue with Watchdog reset when setpoint changed from MCS-STAT. Resolution: Config file is now written in thread not at the time of the change. Also found bug in power up initialization corrected this one too.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.