



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 14.00G 06/11/2013

Updates from previous versions:

New Features:

1. ALL SW- Added a lockout reset si. If in lockout and si is on reset the unit .

Bug Fixes:

1. RTU-Restored the use of set point #157 when the heat pump is in heating mode.
2. RTU-Expanded SCR heat fault test, if there is an SCR fault then all stages are in fault.
3. RTU-With a heat pump & in heating mode reset when the auxiliary heat can come on.
4. RTU-Expanded the heat recovery wheel test to test for exhaust being on if it is specified otherwise the heat recovery wheel will be set to off.
5. RTU-Correction, when in pump down do not change the reversing valve.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.