



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 14.00I

06/17/2013

Updates from previous versions:

Bug Fixes:

1. The RTU single zone logic changed to when in VENT ONLY mode, the fan speed is set to the original value of set point #225. Prior when VENT ONLY mode was entered the fan would ramp down to the minimum setting (value of set point #232, cool mode values).

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.