



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 14.01G 08/30/2013

Updates from previous versions:

Bug Fixes:

RTU:

1. The MOD SCR type of heating no longer requires at least one relay output. If not used the relay cell should be NOT USED and the number of relays should be 0.
2. The magnum heating status displays have been changed. If compressor type is heat pump then the first heating display will be labeled as 'Auxiliary' and the second labeled as 'Emergency' if not an heat pump then the first display will be labeled 'Primary' and the second 'Auxiliary'. If MOD SCR is specified there cannot be a second stage of heating. The second heating display will be labeled 'SCR Steps' and the number of steps will be show if not used then the display will indicate not used.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.