



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 14.01M 09/17/2013

Updates from previous versions:

Bug Fixes:

RTU:

1. When in heating mode and there is no air flow removed the test that required PUMP FAILURE (#105) to be inactive.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.