



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 14.01R 10/11/2013

Updates from previous versions:

New Features:

All:

1. New sensor ADPE500 added, this is the internal temperature sensor for Hartford screw compressors.

Bug Fixes:

All:

1. Problem with sensor TON 1 decimal has been corrected and tested.

HVAC:

2. For the split condenser logic added test to ensure that 2 compressors per suction group could always run. Problem occurred when 2 or more compressors were running and compressors went into a safety or were switched off leaving only 1 compressor running. Now turn off that compressor.

CENT:

3. Added the imbalance amp safety. Same as was implemented for HVAC, use set point #241 to activate this safety.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.