



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 14.01W 12/06/2013

Updates from previous versions:

Bug Fixes:

ALL:

1. All software that has condenser ratio control option. The ration is now 2 decimals not 1.

REFR:

2. Corrections made to the air defrost option, check for proper discharge psi before turning off all evaporators when a defrost cycle starts; added condenser offset when in defrost (set point #140); corrected evaporator rotation issue and do not start an air defrost until minimum compressor run has been reached.

LWC:

3. Corrected the problem with the LWC status display from the Magnum causing a watch dog reset.

RTU:

4. Added to lockout reset, enable if lockout due to fire alarm sensor.
5. When turning off heat stages for MOD GAS types & split manifold; must turn off the valve stages from last to first.

RTU, PAO, & HVAC:

6. Corrected a part winding issue.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.