



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 14.01X 12/20/2013

Updates from previous versions:

Bug Fixes:

RTU:

1. Split Gas Heating worked properly first time it was needed but when the heat stages where turned off the valve status was not correctly set. Resolution: Corrected problem with split gas heating when there were no fixed stages of heating.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.