



SOFTWARE RELEASE NOTES

MCS-MAGNUM
Version 16.10K
01/05/2015

Updates from previous versions:

Bug Fixes:

1. HVAC Firmware: Corrected issue with Turbocor logic - Corrected the test to allow logic to get out of unloading running compressors when all of the running compressors suct/disc ratio is correct. The test was adding incorrectly.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.