



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 17.11B 12/05/2014

Updates from previous versions:

New Features:

1. Released ACU, CENT, HVAC, PAO, REFR, & RTU V16.10C
2. Released All Versions 16.10-D
3. Released RTU 16.10D1 - Lost IO EXV fix in RTU
4. Merged remote-tracking branch 'Server/V16' into Dev-V17

Bug Fixes:

1. Corrected issue in RTU with 2 split manifold valves
2. Changes made to magref.c for allowing air defrost when there are high temperatures.
3. Corrected issue in RTU with split manifold when loading the last stage would not allow loading of heating AO to 100.0%
4. Corrected RTU firmware issue: when Lost IO occurs the EXV start would go to "EXV IN STARTUP" state.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.