



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 17.14G** **03/25/2015**

Updates from previous versions:

Bug Fixes:

1. **Bug Fix: Centrifugal.c. Corrected problem with Warning RO not coming ON after a PURGE_EXCESS_TIME_ALARM. Purge logic must be run after Warning RO OFF general call.**

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.