



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 17.14T 06/01/2015

Updates from previous versions:

Bug Fixes:

1. Expanded MCS-RS485 max address from 20 to 40 (0-39)
2. Corrected the problem in RTU dehumidification when a return air bypass was used as the first stage of reheat. The reheat (2nd stage) would not be activated

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.