



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 17.14U 06/5/2015

Updates from previous versions:

Bug Fixes:

1. **CENT:** The compressor may stay running for a few seconds or minutes with no flow.
2. **RTU:** Currently when unoccupied the smoke purge is not turning on the supply fan. The Unit State changes to Smoke purge, but the Unit Mode stays off.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.