



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 17.14X** **06/15/2015**

Updates from previous versions:

New Features:

Bug Fixes:

1. RTU: When running RTU firmware with Hanbell stepless screw comp, the comp never holds, it is always unloading or loading, even when the comp FLA% is in the dead band.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.