



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 17.16D 08/13/2015

Updates from previous versions:
New Features:

Bug Fixes:

1. CENT v17: Corrected problem with unit showing Run/Stop switch is off but the chiller is running. The relay on the magnum is closed and the vane is closed. Found that the Surge protection logic was overwriting the chiller disable algo.
2. RTU, added a forced flush when a compressor is turned on if specified also corrected the issue of normal flushes when in cooling mode & allow flushes based on suction group

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.