



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 17.19A** **10/01/2015**

Updates from previous versions:

Bug Fixes:

1. **Fix: Prevent buffer overflow causing valid watchdog alarms to report as watchdog #0**
2. **MHRC_CODE: Added missing function prototype (mhrc_modulating_condenser).**
3. **Fix: Prevented MCS Digital Scroll AO types from erroneously causing an invalid voltage when AO is off**
4. **MHRC: Added condenser target offset setpoint**
5. **MHRC: Fix - Prevented condenser from always turning itself on during heating mode.**
6. **MHRC: Prevented comps from shutting off due to flow when switching modes.**
7. **Modified PowerShell Scripts (.ps1) file to include MHRC code and added a select all (firmwares) button.**

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.