



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 17.21B** **11/04/2015**

Updates from previous versions:

Bug Fixes:

1. CPM: Force chillers to rotate when a chiller stages off (if option is selected).
2. MHRC: As per BWW -> Multiaqua wants to be able to set the switching mode time delay (unload_all_comps_delay).
3. MHRC: Problem reported by Mike -Multiaqua. Condenser staying ON 100% when switching from cooling to heating causing a safety trip.
4. MHRC: Problem reported by BWW. Corrected problem with RO chattering immediately after losing flow and unit is "R/S SW OFF" with the CMP "OFF READY".
5. Problem reported by Danny Bonessi -> 2 cmcs unit with a York and a Hanbell: After setting circuit#1DISC Temp SI to "Not Used" the compressor started tripping on Low Discharge superheat.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.