



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 17.21G

12/07/2015

Updates from previous versions:

Bug Fixes:

1. CENT firmware only: If the demand % increases and the compressor was already loaded to the demand limit % previously being written, the compressor will hold at this vane % and never load up to the new Dmd % written by BMS.
2. CPM: Update structure for MCS interpretation of cooling tower capacity control.
3. CPM: Corrected LCD display for condenser info.
4. CPM: Set condenser group vfd AO to the percent wanted if condensers have a vfd AO.
5. In SENSORS.C, fixed the scaling of VOLTS_AC_600_4. It was off by one decimal place.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.