



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 17.21I

12/11/2015

Updates from previous versions:

Bug Fixes:

1. CPM: This fix makes pumps go into anticycle when lockout reset occurs.
2. MHRC: "During Spin Down/Pump down unit went into a vacuum" - Prevent solenoids valves from shutting OFF during Spin Down/ Pump Down and corrected some tab alignment.
3. CPM: Prevents the LCD screens from entering the individual condenser screen when no condensers exist.
4. RTU: Forced Mode - Heating Issue reported by Jeff Mcs... If the Forced-Heat SI is turned OFF the unit does not enter the evap only mode and it remains in in Forced-heat. Logic was getting caught in vent heat mode.
5. SW: We need to have any compressor AO be forced to 0 and its state set to AUTO when unit locks out on a Lost IO.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.