



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 17.21J

12/22/2015

Updates from previous versions:

New Features:

1. All Firmware's - Changed the cmp logic that bumps the exv when the cmp is loading or unloading to allow the end user to define in the cfg when Superheat/Level is OK.

Bug Fixes:

1. CPM: Fix - Default to the lead chiller when no chillers are controllable, and a valve is needed open.
2. CPM: Fix - When staging down pump valves, make sure that uncontrollable chillers' valves are shut down first.
3. ACU.C, corrected the alarm print for circuit alarms, was adjusting line MCS-8
4. RTU; in the status screen changed heading from Auxiliary to Heat Stages
5. RTU, corrected the issue with the modulation of the humidifier valve.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.