



# SOFTWARE RELEASE NOTES

## **MCS-MAGNUM** **Version 17.21L** **01/27/2016**

**Updates from previous versions: 17.21J**  
**New Features:**

### **Bug Fixes:**

1. Alarm Header #37: Heading was misspelled.
2. MHRC: Keep solenoids valves from shutting OFF during Spin Down/ PumpDown and EXV is not in a closing state. (CMP RO OFF timer must be greater than time in sec of STP 62). Corrected some tab alignment.

Released Version 17.21L

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

**Micro Control Systems, Inc.** 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.