



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 17.66G

03/15/2021

Updates from previous versions:17.66F

New Features:

1.

Bug Fixes:

1. Bug Fix. Reported by Mike Leroy - Multiaqua. Customer is getting around the Max Lock Out Reset Per Day feature by changing the time and date from the keypad.
2. Bug Fix. Reported by Mike Leroy - Multiaqua. Customer is getting around the Max Lock Out Reset Per Day feature by changing the time and date from the keypad.
3. Bug Fix LWC. Reported by BCL: Looks like for the pump low/hi amp safeties the alarm is picking up the relay output point. Can we change that to pick up the starting pump alarm# like the pump fault input?
4. BUG FIX issue with rotating coil defrost timer on 1st evap.
5. Bug Fix RTU. Reported by D2: In using the latest firmware I was building a config with reheat control. Two compressors, two circuits. Both circuits have their own AO for mod reheat.

Released Version 17.66G

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.