



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 8.05K** **04/26/2011**

Updates from previous versions:

Bug Fixes:

1. **CENT ONLY:** Changed centrifugal logic to allow the High Amp Unload to function only if the circuit state is not CMP UNLOADED. This will prevent the circuit from entering a HI AMP UNLDING/HOLD state when the compressor first starts.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.