



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 8.05N 05/04/2011

Updates from previous versions:

Bug Fixes:

1. Corrected the problems with lockout based on lost I/O boards.
2. Changed the Unsafe Suction safety to not automatically Lockout on the first time, but to check setpoint #80 to determine if it is configured as a regular safety with automatic reset or a first time Lockout.
3. Modified setpoint #151 "UNLOADED OFF". If the 'Time(sec)' field equals 1, then use the setpoint as an offset from the target setpoint #1. This setpoint value is subtracted from the target to calculate the Unloaded Off value. This new logic makes the Unloaded Off setpoint an offset rather than a fixed value. All existing configs should not require any config change unless the option to use the setpoint as an offset is desired.
4. Corrected tandem EXV logic. Changes were made in 08.05-B1 software but some were lost in later releases. These have been restored.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.