



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.02

12/12/2011

Updates from previous versions:

New Features:

HVAC SOFTWARE ONLY:

1. Added oil recovery option for HVAC. (Refer to BWW's note of this option.)
 - a. In addition:
 - i. The following set points are required: 216, 219, 220, 221, 222, 223, and 224
 - ii. The sequence of the relay outputs must be:
 1. Relay for the VENT (pointed to in the configuration)
 2. Relay for the POT
 3. Relay for the CHARGE
 4. Relay for the first device (these 4 relays are the minimum, the number of devices is entered in the configuration)
 5. Relay for the second device (if number of devices is 2 or greater)
 6. Relay for the third device (if number of devices is 3 or greater)
 7. Relay for the fourth device (if number of devices is 4)

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.