



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.04A

04/02/2012

Updates from previous versions:

New Features:

1. Three new functions are used to modify the setpoint value.
 - a. LCD_edit_value, LCD_edit_value2
 - b. LCD_bms_setpoint_value_adj
 - c. LCD_edit_value2

Bug Fixes:

RTU SOFTWARE ONLY:

1. A change from 9.03B that kept the heat pump running if low ambient has been fixed.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.