



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.04F

05/24/2012

Updates from previous versions:

New Features:

1. A test has been added to check if the leaving temp sensor and the SP_FREEZE_PROT setpoint are active before shutting the unit down. This can be due to a low TEMP condition while in PUMP DOWN logic.

RTU SOFTWARE ONLY:

2. A conditional compile has been added to the RTU code. RTU heat states were causing a compile error.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.