



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.10G

06/27/2012

Updates from previous versions:

New Features:

RTU SOFTWARE ONLY:

1. A new type of heater has been added to handle the Duccommon. It is very similar to the existing Mod Gas except it has only 1 RO, it does not have a low & high fan and there is no warm up state. 'MOD GAS1' is the new type which indicates 1 RO & MOD GAS2 exists with 2 RO per stage.

Bug Fixes:

CENT SOFTWARE ONLY:

1. A problem with hot gas control has been corrected. This problem involved when the 'vain control not amps control' is used.

RTU SOFTWARE ONLY:

2. The supply fan will now turn off if run/stop is stop.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.