



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.10I

07/06/2012

Updates from previous versions:

RTU SOFTWARE ONLY:

New Features:

1. Additional reheat flush logic has been added.
2. Return fan logic has been added. This means if no there is no exhaust fan, then it will track the supply fan.
3. An alarm was added. If the supply fan would fault, then the system will generate the 'supply fan fault' and will continue to run.
4. A heat wheel fault has been added. If the fault is on, the heat wheel is stopped.

Bug Fixes:

1. In dehumid mode, a change was made so that only one compressor per suction group can be turned on.
2. If the unit is not running, it will now automatically set the relief damper to 0%

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.