



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.10O

07/28/2012

Updates from previous versions:

Bug Fixes:

RTU SOFTWARE ONLY:

1. Software dealing with the heating functions of RTUs has been modified.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.